

OPLYSNINGER OM SIKKER BRUG AF SVHC

REACH-ARTIKEL 33 OPLYSNINGER OM STOFFER, DER ANSES FOR AT VÆRE SÆRLIGT PROBLEMATISKE

Kære kunde

REACH-forordningen (forordning EF 1907/2006) artikel 33, stk. 1 har til formål at give kunderne af leverede produkter mulighed for at træffe relevante risikostyringsforanstaltninger, der måtte opstå som følge af forekomsten i artikler af stoffer, der anses for at være særligt problematiske (SVHC'er), som er opført på den nuværende kandidatliste til godkendelse, for at sikre deres sikre brug.

FORD støtter de underliggende mål for REACH generelt og artikel 33, stk. 1, specifikt, hvilket er i overensstemmelse med vores egen forpligtelse til at fremme ansvarlig fremstilling, håndtering og brug af vores produkter.

Identifikation af SVHC'er

Så vidt vi ved, baseret på oplysninger fra vores forsyningskæde og vores egne produktdata, er de SVHC'er, der findes i komponentartikler på mere end 0,1 % w/w, dem, der er vist på den relevante "SVHC-liste" for det/den specifikke køretøj/del.

Specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er

Hvis det er relevant, tilføjes specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er, til den relevante "SVHC-liste" for det/den specifikke køretøj/del.

Generelle sikkerhedsoplysninger for artikler

Hvert FORD-køretøj er forsynet med en manual, som indeholder oplysninger om sikker brug til ejere/operatører af køretøjet. FORD-oplysninger om reparation og eftersyn af køretøjer og originale dele indeholder også oplysninger om sikker brug til servicepersonale.

Der hvor de er til stede i dele af dette køretøj, er SVHC'erne, der er vist på den relevante "SVHC-liste" for det/den specifikke køretøj/del, indarbejdet på en sådan måde, at potentiel eksponering for kunderne er minimeret, og fare for mennesker eller miljøet kan udelukkes som så længe køretøjet og dets dele anvendes efter hensigten, og reparationer, eftersyn og vedligeholdelse udføres efter tekniske instruktioner til disse aktiviteter og god praksis i branchen.

Et udrangeret køretøj må kun bortskaffes lovligt i EU på en autoriseret behandlingsfacilitet (ATF). Køretøjsdelene skal bortskaffes i overensstemmelse med gældende lovgivning og lokal myndighed.

Model: New Ford Explorer

SVHC-liste baseret på ECHA-kandidatliste pr. 1. juli 2024

Specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er

Der kræves ingen specifikke sikkerhedsoplysninger - følg generelle sikkerhedsoplysninger for artikler.

Commodity	REACH SVHCs
A/C Compressor	Lead [7439-92-1]
A/C Lines, Receiver Drier and Accumulator	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
ABS/ESC Module	Lead [7439-92-1]
Accessories	1,2-Dimethoxyethane [110-71-4]
	Lead [7439-92-1]
Adaptive Cruise Control	Lead [7439-92-1]
	Melamine [108-78-1]
Air Brakes	Lead [7439-92-1]
Antenna	Lead [7439-92-1]
Battery	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Body Side Interior Trim (Hard Trim)	C,C'-azodi(formamide) [123-77-3]
Body Structure - Body Side Assembly	Bumetizole [3896-11-5]
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Lead [7439-92-1]
Body Structure - Front End Structure	Lead [7439-92-1]
Brake Actuation	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Bumpers Beams (Un-Exposed) - Front/Rear	Lead [7439-92-1]
CHMSL	Lead [7439-92-1]
Coil Spring (Front, Rear)	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Console Floor/Rear	C,C'-azodi(formamide) [123-77-3]
Cooling Fans	Lead [7439-92-1]
Cooling Hoses & Bottles	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
Door Handles	Lead [7439-92-1]
EDS Wiring Assembly & Components	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Electrified Drivetrain	Lead [7439-92-1]
Electro/Mechanical Devices - Security	Lead [7439-92-1]
Electronic Control Panel and CCH	Lead [7439-92-1]
Electronic Modules - Amplifiers	Lead [7439-92-1]
Electronic Modules - Displays	Lead [7439-92-1]

Electronic Modules - Door Zone	Lead [7439-92-1]
Electronic Modules - Power Decklid/Liftgate (PLG)	Lead [7439-92-1]
Electronic Modules - Seat Control	Lead [7439-92-1]
Electronic Modules - Steering	Lead [7439-92-1]
Electronic Modules - Suspension	Lead [7439-92-1]
Electronic Modules - SYNC	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
Engine Water Pumps	Lead [7439-92-1]
Evaporator and Blower Assembly (HVAC Module)	Lead [7439-92-1]
Front / Rear Door Trim	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Fuel Door	Lead [7439-92-1]
GOR and Radiator Support	Diocetyl tin dilaurate [3648-18-8]
Headlamp / Side Marker	Lead [7439-92-1]
Headliner / Sunvisor	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Heat/Sound Insulators - Dash/Tunnel/Wheelhouse/Hood	Melamine [108-78-1]
Hinges and Checks - Side Door	Cobalt sulphate [10124-43-3]
I/S Mirror	Lead [7439-92-1]
Instrument Cluster	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Interior Lighting	Lead [7439-92-1]
	TBBA [79-94-7]
IP Substrate and Ducts	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Knuckle (Front, Rear)	Lead [7439-92-1]
Labels	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
Latches - Hood, Decklid and Liftgate Latches	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Locks	Lead [7439-92-1]
Mirrors	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
	TBBA [79-94-7]
Overhead Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Park Assist	Lead [7439-92-1]
Pedal Box	Lead [7439-92-1]
Pedestrian Alert System (PAS)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Powertrain Control Module (PCM/EEC/ ECM)	Lead [7439-92-1]
PT Mounts	Lead [7439-92-1]
Rain and Daylight Sensor	Lead [7439-92-1]
Restraint Electronics	Lead [7439-92-1]
RKE Module	Lead [7439-92-1]
	TBBA [79-94-7]
Sealing - Door Dynamic Seals	Octamethylcyclotetrasiloxane [556-67-2]
Seat Belts (Front and Rear)	Disodium-octaborate [12008-41-2]

	Lead [7439-92-1]
Seats - Foam - Cut and Sew	Bumetrizole [3896-11-5]
Seats - Structures	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Shock Absorbers	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
Side Air Bag (SAB) and Curtain Air Bag (CAB)	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Side and Rear Vision (BLIS)	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Speakers / Tweeters	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
Steering Column	Lead [7439-92-1]
Steering Gear and Linkage	Lead [7439-92-1]
Steering Wheel, Drive Air Bag	Lead [7439-92-1]
Suspension Link Components	Imidazolidine-2-thione [96-45-7]
Switches - General Use	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Switches - Headlamp. Window & Door	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Switches - Steering Column	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
Taillamp / Redundant	Lead [7439-92-1]
Temperature Sensors - Climate	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Tires	Lead [7439-92-1]
Window Regulator	Lead [7439-92-1]
Wiper Assembly (Rear, Front) & Washer System	Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
	Lead [7439-92-1]
xEV - Power Cabling	Bumetrizole [3896-11-5]
	Octamethylcyclotetrasiloxane [556-67-2]
xEV - Traction Battery (as Shipped)	Lead [7439-92-1]
xEV - Traction Battery Charging	Lead [7439-92-1]